

CUSTOMER INFORMATION BULLETIN



Rocket Change of Component

Dear Customer,

Unfortunately do to a supply issue, for the short term, we are unable to supply the usual guide wire in the following Rocket Medical Seldinger Kits.

R54544-12-SG, R54544-12-PK, R54549-16-PK, R54544-18-SG, R54544-18-PK, R54549-20-PK

The current guide wire is a 0.035" diameter, 70cm long, stainless steel guide wire with thumb feed introducer with 10cm, 20cm and 30cm distance marks on the J tip.



Until the above guide wire can be supplied, Rocket will be supplying a is a 0.035" diameter, 70cm long, stainless steel guide wire, with NO thumb feed introducer or depth marks



We apologise if this causes an inconvenience and hope to have the original one back in the packs by early next year.

Customer Information Bulletins on all of our products can be found on our web site at:

<http://sales.rocketmedical.com/support/customer-information-bulletins>

If you have any questions, please contact the Customer Services Team for assistance:

Tel: +44 (0) 191 419 6988. Fax: +44 419 6889. Email: customerservices@rocketmedical.com

